

## Attaching Press Tools

A different chuck and die is required for all types of sizes of fasteners and clips. Tools are simple to change in presses to allow the assembly of many fasteners on one press (L part numbers to suit M369 hand press), (SP00 not suitable for H50 H/duty press).

### SP EYELET AND WASHER



#### FASTENER

\*SP00  
SP0  
SP1  
SP3  
SP4  
SP6  
SP7  
SP9



#### CHUCK

T1669  
T1611(L)  
T1544(L)  
T1532(L)  
T1613  
T1542  
T1538  
T1615



#### DIE

T1670  
T1612  
T1545  
T1533  
T1614  
T1543  
T1539  
T1616

(L) is for M325, M369 Where applicable.  
\*Not suitable for H50

### DURABLES

Socket & button	T1410C	T1401
Stud & eyelet	T1412	T1407

### ROPE END CLIP

550-2-7	T1241	T1242
550-2-8	T1243	T1244

### ROPE SPLICE CLIP



550-21-1 / 550 - 21 - 4  
550-21-2 / 550 - 21 - 5  
550-21-3



T1261  
T1263  
T1265



T1262  
T1264  
T1266

### CONVERTER - Press tools to hand tools



192



194

## Hand Tools

Hand tools are used when volume requirements do not warrant the purchase of a press, or press assembly is not practical or possible.

### SP EYELET AND WASHER



FASTENER	TOOL
SP00	N/A
SP0	180
SP1	181
SP3	183
SP4	184
SP6	186
SP7	187
SP9	189

### LIFT THE DOT



708A Socket 151-608



952 Stud 169B



895 Stud 171

### COMMONSENSE



400 Eyelet 450-400



412 Stud 171

### DURABLE



Button	164
Eyelet	164